


### Calibrator

Measuring the single parameter of pipe thread.

How to order: Qty, Nominal size, Class, Marking and so on.
Also special gages on application.



Range		Туре	Order No.
	Micro head 0-25x0.002mm	JYY-1	2620-1071

# Pit Depth Gage

Measuring the depth of concave and crackle of casing and oil pipes.

How to order: Qty, Type, Marking and so on.

Also special gages on application.



Range	Resolution	Type	Order No.
0-3mm	0.01mm	ATY	2620-1073

## **Lead Gage Setting Standards**

Setting the measuring gauges before measuring the screw pitch.

How to order: Qty, Type, Marking and so on.

Also special gages on application.



Specification	Туре	Order No.
1:16, 5TPI	LJK1	2620-1081
1:16, 8TPI	LJK2	2620-1082
1:16,10TPI	LJK3	2620-1083
1:6, 4TPI	LJK4	2620-1084
1:4, 4TPI	LJK5	2620-1085
1:4, 5TPI	LJK6	2620-1086

### **Thread Height Setting Standards**

Setting the measuring gauges before measuring the thread height.

How to order: Qty, Type, and so on. Also special gages on application.





Specification	Туре	Order No.
1:16, 5TPI	CGK1	2620-1091
1:16, 8TPI	CGK2	2620-1092
1:16, 10TPI	CGK3	2620-1093
1:6, 4TPI (V-0.038R,V-0.050)	CGK4	2620-1094
1:4, 4TPI (V-0.038R,V-0.050)	CGK5	2620-1095
1:4, 5TPI (V-0.040)	CGK6	2620-1096

# **Measuring Points for Gages**

Choosing suitable measuring point according to measured thread specification.

How to order: Qty, Type, and so on. Also special gages on application.



Diameter	Type	Order No.
1.448mm	CLT1	2620-1101
1.575mm	CLT2	2620-1102
1.829mm	CLT3	2620-1103
2.286mm	CLT4	2620-1104
3.658mm	CLT5	2620-1105