

Buttress Casing Thread Vanishing Point Gauge

Measuring the length of buttress casing thread to make sure enough length of outer thread and knowing that the thread is reaching the thread vanishing point.

How to order: Qty, Nominal size, Class, Marking and so on.
Also special gages on application.

Range	Resolution	Type	Order No.
0-4mm	0.01mm	XSG	2620-1051



Coaxial Meter

Measuring the coaxial variation between the central axis of the connecting of casing tubes and oil pipes.

How to order: Qty, Nominal size, Class, Marking and so on.
Also special gages on application.

Range	Resolution	Type	Order No.
+/-2mm	0.01mm	JTG	2620-1052



Drill Pipe Coaxiality Measuring Gage

Measuring the coaxial variation of the connecting drill pipes.

How to order: Qty, Nominal size, Class, Marking and so on.
Also special gages on application.

Range	Resolution	Type	Order No.
0-10mm	0.01mm	XX	2620-1053



Scriber on the Measuring Threads

How to order: Qty, Nominal size, Class, Marking and so on.
Also special gages on application.

Range	Type	Order No.
0-4inch	HXY	2620-1054

