


## **Pitch Diameter Gauge for External Thread**

Measuring the pitch diameter of external thread.

How to order: Qty, Nominal size, Class, Marking and so on.

Also special gages on application.

Range	Туре	Order No.
< 5-1/2"	ZJY5-W	2620-1061
2 3/8-20"	ZJY20-W	2620-1062




## **Pitch Diameter Gauge for Internal Thread**

Measuring the pitch diameter of internal thread.

How to order: Qty, Nominal size, Class, Marking and so on. Also special gages on application.

Range	Туре	Order No.
< 5-1/2"	ZJY5-N	2620-1063
2 3/8-20"	ZJY20-N	2620-1064



## **Screw Thread Profile Microscope**

Measuring the half of thread angle.

How to order: Qty, Nominal size, Class, Marking and so on.
Also special gages on application.

Range	Туре	Order No.
Magnifying Power 25.6X	СКҮ	2620-1070

