


Taper Measuring Instruments for Internal Thread

How to order: Qty, Nominal size, Class, Marking and so on.
Also special gages on application.

Range	Type	Order No.
1-6 in (25.4-152.4 mm) Indicator 0-1 in Grad: 0.001 in	JZN 06	2620-1011
5-1/2-16 in (139.7-406.4 mm) Indicator 0-0.5 in Grad: 0.001 in	JZN 16	2620-1012



Thread Pitch Measuring Instruments/Lead Gages

How to order: Qty, Nominal size, Class, Marking and so on.
Also special gages on application.

External Thread Pitch Gages - Used for all external thread

Range	Type	Order No.
0.5-4 in (12.7-101.6 mm) Grad: 0.01 mm	W R W	2620-1031



Internal Thread Pitch Gages

Internal Thread Pitch Gages - Used for sizes smaller than 5 1/2" internal thread

Range	Type	Order No.
0.5-4 in (12.7-101.6 mm) Grad: 0.01 mm	W R N	2620-1032



Thread Height Measuring Instruments

How to order: Qty, Nominal size, Class, Marking and so on.
Also special gages on application.

Thread Height Gage - Used for all external Thread and internal thread size smaller than 5 1/2"

Range	Resolution	Type	Order No.
0-4mm	0.01mm	W G W	2620-1041



Thread Height Gage - Used for internal Thread size smaller than 5 1/2" internal thread

Range	Resolution	Type	Order No.
0-4mm	0.01mm	W G N	2620-1043



Buttress Casing Thread Height Gages-Used for all buttress internal and external thread

Range	Resolution	Type	Order No.
0-4mm	0.01mm	W G W 2	2620-1042

