

Digital Multimeters


- 3 1/2 digits LCD , Max. reading of 1999.
- Low Battery indication.
- Overload protection.
- Audible continuity.
- Safety CAT II 600V.
- Battery: 1x9V(6F22).

Order No.856-0030

Descriptions	Measuring Ranges	Accuracy
Voltage DC	200m-2-20-200-600V	+/- 0.5%
Voltage AC	200-600V	+/- 1.2%
Current DC	2m-20m-200m-10A	+/- 1.2%
Resistance (OHM)	200-2K-20K-200K-2MΩ	+/- 1.0%
Battery Check	1.5V, 9V	
Diode Check	2.8V / 1 mA	
Size / Weight	130x68x32mm / 135g	
Mfr's #	EM370	

Auto Range


- 3 1/2 digits LCD , Max. reading of 1999.
- 7 Functions for DCV, ACV, DCA, ACA, OHM, Diode Check & Buzzer.
- Auto Range.
- Auto power off.
- Safety CAT II 600V.
- Battery: 2x1.5V(AAA)


Order No.856-0058

Descriptions	Measuring Ranges	Accuracy
Voltage DC	200m-2-20-200-600V	+/- 0.7%
Voltage AC	2-20-200-600V	+/- 1.2%
Current DC	200μA-2000μA-20m-200m-2-10A	+/- 1.8%
Current AC	200μA-2000μA-20m-200m-2-10A	+/- 1.2%
Resistance (OHM)	200-2K-20K-200K-2M-20MΩ	+/- 1.0%
Diode Check	2.8V/1 mA	
Size / Weight	150x54x25mm/160g	
Mfr's #	EM308	

Intelligent One Switch Meter


- Auto selecting DCV, ACV, OHM & Buzzer.
- Auto Range.
- 3 3/4 digits LCD, Max. reading 3999.
- Overload protection.
- Auto power off.
- Safety CAT II 300V.
- Battery: 1x9V(6F22).

Order No.856-0070

Descriptions	Measuring Ranges	Accuracy
Voltage DC	4-40-400V	+/- 0.8%
Voltage AC	4-40-400V	+/- 1.2%
Resistance (OHM)	0 ~ 400 Ω	+/- 1.0%
Size / Weight	155x70x39mm/230g	
Mfr's #	EM50	

Digital Multimeters


- 3 1/2 digits LCD , Max. reading of 1999.
- Low Battery indication.
- Overload protection.
- Safety CAT II 600V.
- Battery: 1x9V(6F22).

Order No.856-0040

Descriptions	Measuring Ranges	Accuracy
Voltage DC	200m-2-20-200-600V	+/- 0.5%
Voltage AC	200-600V	+/- 1.2%
Current DC	2m-20m-200m-10A	+/- 1.2%
Resistance (OHM)	200-2K-20K-200K-2MΩ	+/- 1.0%
Battery Check	1.5V, 9V	
Diode Check	2.8V / 1mA	
Size / Weight	130x68x32mm / 135g	
Mfr's #	EM390	

Auto Range


- 3 1/2 digits LCD, Max. reading 1999.
- Low battery indication.
- Overload protection.
- Audible continuity.
- Auto Range.
- vAuto power off.
- Safety CAT II 600V.

Accessories: Test Lead; 2x1.5V (AA) Battery.

Order No.856-0052

Descriptions	Measuring Ranges	Accuracy
Voltage DC	200m-2-20-200-600V	+/- 0.7%
Voltage AC	2-20-200-600V	+/- 1.2%
Current DC	20m-200mA	+/- 1.2%
Current AC	20m-200mA	+/- 0.8%
Resistance (OHM)	200-2K-20K-200K-2M-20MΩ	+/- 1.0%
Diode Check	2.8V / 1mA	
Size / Weight	127x70x30mm / 145g	
Mfr's #	EM302	

Digital Clamp Meter


- 3 1/2 digits LCD, Max. reading 1999.
- Data-hold function.
- Low battery indication.
- Overload protection.
- Audible continuity.
- 7 functions, 8 ranges.
- DCA & ACA measurement.
- Battery: 1x9V(6F22).

Order No.856-0104

Descriptions	Measuring Ranges	Accuracy
Voltage DC	1000V	+/-1.0%
Voltage AC	750V	+/-1.2%
Current DC	200-1000A	+/-2.0%
Current AC	200-1000A	+/-2.0%
Resistance (OHM)	200 Ω	+/-1.0%
Frequency	2KHz (+/-2.5%)	+/-2.5%
Size / Weight	250x99x43mm / 400g	
Mfr's #	EM204	

Digital Clamp Meters



- 3 1/2 digits LCD, Max. reading 1999.
- 4 Functions, 5 Ranges.
- Data-hold function.
- Audible continuity.

Accessories:

Test Lead; 1x9V(6F22) Battery; Carrying case;
Users Manual

Order No.856-0117

Descriptions	Measuring Ranges	Accuracy
Voltage AC	200-600V	+/- 1.5%
Current AC	200-600A	+/-2.0%
Resistance (OHM)	200 Ω	+/-12%
Clamp size	33mm(Max.)	
Size / Weight	208x90x40mm / 290g	
Mfr's #	2017	

Digital Clamp Meters



- 3 1/2 digits LCD, Max. reading 1999.
- 6 Functions, 8 Ranges.
- Data-hold function.
- Low battery indication.
- Overload protection.
- Audible continuity.

Accessories:

Test Lead; 1x9V(6F22) Battery; Carrying case;
Users Manual

Order No.856-0127

Descriptions	Measuring Ranges	Accuracy
Voltage DC	600V	+/- 0.8%
Voltage AC	450V	+/-1.0%
Current AC	20-200-400A	+/-2.0%
Resistance (OHM)	2K-200K Ω	+/-1.2%
Diode Check	3.2V/1.2mA	
Size / weight	198x63x28mm / 241g	
Mfr's #	EM87	

Digital Photo Tachometer



Order No.856-0204

Functions	Measuring Ranges
Display	LCD
Rotative velocity	2.5 - 99.999 Round/Min
Resolution	1r/min (over 1000RPM)
Accuracy	+/- (0.05% $\pm$ 1d)
Sampling(SEC)	1.0 (over 60RPM)
Memory	Max. / Min. / Last value
Battery	4 x 1.5V (AA)
Size	190x72x37mm
Mfr's #	2234A

Humidity/Temperature Meter



Order No.856-0211

Functions	Measuring Ranges
Display	LCD
Humidity	10 - 100
Temperature	-10 - 65°C
Resolution	+/-0.1
Accuracy	1 or 3%RH
Memory	Max. , Min., Last value
Battery	4 x 1.5V (AA)
Size	220 x 72 x 37mm
Mfr's #	HC-601C

Multifunctional Sound Level Meter



Order No.856-0221

Functions	Measuring Ranges
Display	LCD
Sound level	30 - 130dB
Weighting	A C. Linear Filter
Function	SL. Leq. LN
Detection characteristics	Fast/Slow
Sound level alarm set	30 - 130dB
Accuracy	+/- 0.8dB
Resolution	0.1dB
Battery	4 x 1.5V (AA)
Size	212 x 69 x 32mm
Mfr's #	S4001

Digital Lux Meter



Order No.856-0231

Functions	Measuring Ranges
Display	LCD
Luminosity	0 ~ 50000 LUX
Accuracy	+/- (5%+1d)
Resolution	1 LUX
Overload Display	1
Battery	1x9V (6F22)
Size	105 x 70 x 20mm
Mfr's #	XL-101