

Thread Height Measuring Instruments

How to order: Qty, Nominal size, Class, Marking and so on.
Also special gages on application.

Thread Height Gage - Used for all external Thread and internal thread size smaller than 5 1/2"

Range	Resolution	Type	Order No.
0-4mm	0.01mm	W G W	2620-1041



Thread Height Gage - Used for internal Thread size smaller than 5 1/2" internal thread

Range	Resolution	Type	Order No.
0-4mm	0.01mm	W G N	2620-1043



Buttress Casing Thread Height Gages-Used for all buttress internal and external thread

Range	Resolution	Type	Order No.
0-4mm	0.01mm	W G W 2	2620-1042

